



EXHIBIT # 69

Professional Horizontal Drilling, LLC

October 17, 2018

RE: Directional bore for side sewer at 4611 NE 178th St Lake Forest Park, WA 98155

Steve, after reviewing the job site we suspect that there is not enough elevation to keep the 3% grade for your side sewer installation via directional bore. The survey must be done to determine what elevation is there and the percentage.

Even if there is a 3% grade we can not guarantee that install. The minimum grade percentage that we can start from is 5% in the good ground conditions.

Sincerely,

Sergey Chaban
GM

253-217-9018

cc:

THE BEST DIRECTIONAL DRILLING COMPANY OF THE NORTHWEST
PO BOX 15132 MILL CREEK, WA 98082