



INSPECTOR'S DAILY REPORT

City of Lake Forest Park - Staunton Cove Short Plat

Daily Information	
Inspector's Name:	Michael Maranan Date: 9/16/2016
Inspector's Shift Hours:	8 a.m. to 5 p.m. - Periodic
Weather:	a.m.: p.m.: 70±°F, mostly cloudy
Prime Contractor:	Universal Land Construction Company
Representative & Title:	Mike Johnson, Project Manager
Contractor's Work Activity	
Location of Work:	18623 40th Place NE
Description of Work:	Construction of Temporary Erosion and Sedimentation Control (TESC)

Inspection			
Time	What was inspected?	In Conformance?	Comments / Action
-	TESC	-	• Site looks good - no ongoing construction at this time.

Inspection	
Diary	
Time	Discussion
2:30 PM - 2:40 PM	<p>Approximate time of arrival on site was 2:30 PM. No one was working on site at this time.</p> <p>The following TESC items have been noted:</p> <ol style="list-style-type: none"> Discharge: No discharge. Approximate amount of precipitation since last inspection: <u>0.02</u> inches* Approximate amount of precipitation in the past 24 hours: <u>0.0</u> inch* * Based on nearby rain gauge as recorded by King County. Construction Entrance: Needs maintenance; however, currently not used - OK. Perimeter protection: OK. Tree protection: Silt fence was used - OK. Silt fence: OK. Inlet protection: N/A on site. Stabilization of exposed soils: Stockpiles were covered in plastic, and exposed areas have been hydroseeded - OK. Dust control: OK. Source control: OK <p>Inspector left at approximately 2:40 PM.</p>

Michael Maranan
(Inspector's Printed Name)

Signature

9/16/2016
Date